
HYVA QUILL SHAFT

QUILL SHAFT





Parts list				
No.	Partno.:	Description	Qty.	
1		Quill shaft	1	
2		Circlip E 45	1	
3		Bearing back-up ring	1	
4		Ball bearing 45x75x16	1	
5		Bearing-holding flange	1	
6		Gasket	1	
7		Gasket between flange and gearbox	1	
8		O-ring 3068	1	

General	Intorm	ations
Concid		GUIOT

N.B. The TCE Ø 10x1 plug can be removed from the transmission to guarantee adequate lubrication for the PTOs that are working in demanding conditions (high power and turns and/or prolonged working times). In the shaft kit assembly phase, confirm the correct position of the O-R pos. 8 and gasket pos. 7

Type of Gearbox				
ZF	12AS 1800+INTARDER 16AS 2631+INTARDER			



